



Barcode scanner BC626

Guide de démarrage rapide




W010F01

Enter Setup



France




W016C01

Enable Interleaved 2 of 5



W0C6C00

Disable check digit Verification



W010F00

Exit Setup